

In the Specification:

Please replace paragraph [0038] with the following:

It should also be noted that the roll center shown in FIG.4 is intersected by the vertical centerline 72 of the vehicle body 28. The roll center 68 intersects the centerline 72 because the suspensions on each side of the vehicle body 28 are symmetrical with one another. In some instances there is an advantage to making the suspensions non-symmetrical and thereby cause the roll center 68 to be disposed on one side of the vehicle centerline 72. In addition, under certain loading or body movement conditions, the roll center 68 may move to either side of the vehicle centerline 72.